



M059

Section: MOUNTFIELD 725M CHASSIS

Pos.	Quantity	Spare part No	Description	Kit	Notes	New
	2657					
1	1	1136-1085-01	Side frame-RH			
2	1	1136-1086-01	Side frame-LH			
3	1	1136-1100-01	Support			
4	2	1136-1005-01	Clamp			
5	6	1136-0815-01	Screw			
6	2	1136-0988-01	Reinforcement			
7	12	1136-0815-01	Screw			
8	1	1136-1094-01	Reinforcement			
9	4	1136-0815-01	Screw			
10	1	1136-1101-01	Support			
11	6	1136-0815-01	Screw			
12	1	1136-0421-01	Clamp			
13	2	9847-7809-16	Screw			
14	1	1136-1102-01	Support			
15	2	1136-0815-01	Screw			
16	1	9997-0825-16	Screw			
17	1	1136-0014-01	Washer			
18	1	9747-0831-02	Lock nut			
19	1	1136-1018-01	Support			
20	4	9997-0630-12	Screw			
21	4	9747-0631-02	Lock nut			
22	1	1136-1010-01	Angle bracket			
23	1	9997-0616-16	Screw			
24	1	9747-0631-02	Lock nut			
31	1	1136-1090-01	Plate-rear			
32	4	1136-0815-01	Screw			
33	2	1136-0987-01	Reinforcement			
34	4	1136-0815-01	Screw			
35	2	1136-1007-01	Clamp			
36	2	1136-0825-01	Screw			
37	2	9699-0090-02	Flat washer			
38	2	9747-0831-02	Lock nut			
41	1	1136-0960-01	Spring			
42	1	1136-0962-01	Spring			
43	2	1136-0999-01	Angle bracket			
44	2	9847-8116-16	Screw			
45	1	1136-0997-01	Rack			
46	2	9997-0616-16	Screw			
47	2	9739-0631-22	Nut			