

Illustration Antrieb




Illustration Antrieb

Bild Nr.	St.- Zahl	Teile Nr.	Beschreibung
1	1	3915006	Mutter
2	1	3916006	Scheibe
3	1	3906053	Schraube
4	1	4198015A	Flexibel welle
5	1	4198041A	Rohr Ø22
6	4	3801011	Schraube
7	4	3819006	Scheibe
8	4	3918010	Scheibe
9	1	3960014	Schraube
10	1	4174275R	Klinge
11	1	60010143R	Keilriemen
12	1	4199011A	Einsatz
13	1	4162042A	Handgriff
14	1	4199004	Feder
15	1	4199024B	Zundanker
15	1	4199045R	Zundanker
16	2	4199005A	Distanzring
17	1	4199026B	Deckel
17	1	4199035R	Deckel
18	1	4199040AR	Mähköpfe tap'n go mit 2 nylonfäden Ø2
19	1	60032012	Schutz
20	1	4198167	Flansch
21	1	4198168R	Deckel
22	1	3914003	Mutter
23	1	3801013	Schraube

Illustration Motor






Illustration Motor

Bild Nr.	St.- Zahl	Teile Nr.	Beschreibung
1	1	60030008R	Dichtung
2	1	60030016R	Burste
3	1	60020008	Lufferrad
4	1	60030007R	Motor
5	1	2317025	Schalter
6	1	60022032	Kabel kit
7	1	60032032	Motorgehäuse
8	1	60020014	Gashebel