

Brand **Flymo**

date **25/02/04**

**SUBJECT: Hedgetrimmer Spare**

<b>Products Affected:</b>	<b>HT 42</b>	<b>9648147-01</b>
	<b>HT420</b>	<b>9648143-01</b>
	<b>HT450</b>	<b>9648144-01</b>
	<b>HT600</b>	<b>9648153-01</b>
	<b>HT510</b>	<b>9648159-01</b>



**Only the spares listed below are available for these products.  
If any other repairs are necessary contact the warranty department for  
exchange authorisation.**



Safety Guard



Bladesheath



Bladeset - Gear Housing

Product	Spares Available	
HT42	Safety Guard	5128242-02
	Bladesheath	5131196-01
	Bladeset - Gear Housing	5128241-01
HT420	Safety Guard	5128242-01
	Bladesheath	5131196-01
	Bladeset - Gear Housing	5128241-01
HT450	Safety Guard	5128242-01
	Bladesheath	5131196-01
	Bladeset - Gear Housing	5128241-02
HT510 / 600	Safety Guard	5128242-01
	Bladesheath	5131196-02
	Bladeset - Gear Housing	5128241-03

service information: bulletin