



Section: PFS FRONT TILLER ART.NO 14-1979-11

Pos.	Quantity	Spare part No	Description	Kit	Notes	New
			1979			
4	1	1489-0584-01	Bow			
5	2	9997-0616-16	Screw			
6	2	9683-0025-02	Lock washer			
7	2	9799-0631-02	Nut			
8	8	9997-0616-16	Screw			
9	1	1489-0580-01	Housing			
10	12	1482-0884-01	Screw			
11	1	1489-0581-01	Gate			
12	2	1489-0582-01	Hinge			
13	12	9739-0631-22	Nut			
14	1	1482-0092-00	Pin			
15	1	1489-0578-01	Tube			
16	1	1482-0827-01	Pin			
17	1	9598-0002-02	Pin lock			
18	2	9997-1065-12	Screw			
19	1	9997-0860-16	Screw			
20	4	9997-0630-12	Screw			
21	8	9683-0025-02	Lock washer			
22	8	9799-0631-02	Nut			
23	1	1489-0577-01	Side member-L.H.			
24	2	9683-0040-02	Lock washer			
25	2	9799-1031-02	Nut			
26	1	9683-0030-02	Lock washer			
27	1	9799-0831-02	Nut			
28	4	9683-0025-02	Lock washer			
29	4	9799-0631-02	Nut			
30	1	1489-0576-01	Side member-R.H.			
31	4	1489-0507-01	Bushing			
32	2	9997-0855-12	Screw			
33	2	9747-0831-02	Lock nut			
34	4	1482-0785-01	.Blade-R.H.			
35	2	1489-0579-01	.Blade tube			
36	16	9987-5119-16	.Screw			
37	16	9794-5131-02	.Nut			
38	4	1482-0783-01	.Blade-L.H.			
39	1	1489-0587-01	Rotor assy-R.H.			
40	21	9799-0531-02	.Nut			
41	1	1482-0248-01	.Plastic plug			
42	1	1482-0554-01	.Bushing			
43	1	9747-0831-02	.Lock nut			
44	1	1482-0214-01	.Oil-seal			
45	1	1489-0588-01	.Cover-R.H.			
46	1	9549-0017-00	.Ball bearing			
47	1	1489-0589-01	.Bushing			
48	1	9594-0055-00	.Locating pin			
49	1	1489-0585-01	.Sprocket			
50	1	1489-0585-01	.Sprocket			
51	1	9549-0017-00	.Ball bearing			
52	1	9594-0055-00	.Locating pin			
53	1	1489-0482-01	.Reducing pipe			
54	1	1489-0499-01	.Gasket			
55	1	1489-0598-01	.Steel gasket			
56	1	1489-0499-01	.Gasket			
57	1	9699-0060-02	.Flat washer			
58	1	1482-0843-01	.Needle bearing			
59	1	1489-0586-01	.Sprocket			
60	1	1482-0843-01	.Needle bearing			
61	1	1489-0586-01	.Sprocket			
62	1	9699-0060-02	.Flat washer			
63	1	1489-0592-01	.Chain			
64	1	1489-0593-01	.Bushing			
65	1	1489-0599-01	.Chain tightener			
66	1	1482-0629-01	.Spring			
67	1	1482-0485-01	.Needle bearing			
68	1	1489-0594-01	.Output shaft			
69	1	1489-0595-01	.Flange			

Section: PFS FRONT TILLER ART.NO 14-1979-11

Pos.	Quantity	Spare part No	Description	Kit	Notes	New
1979						
70	1	1482-0485-01	.Needle bearing			
71	1	1489-0596-01	.Cover-L.H.			
72	1	1482-0214-01	.Oil-seal			
73	1	9997-0855-12	.Screw			
74	21	9997-0510-16	.Screw			
75	1	1489-0575-01	Chain case assy			
76	4	1489-0507-01	Bushing			
77	1	1489-0597-01	Rotor assy-L.H.			
78	4	1482-0824-01	Screw			
79	2	9699-0024-02	Flat washer			
80	2	9699-0024-02	Flat washer			
81	1	9747-0531-02	Nut			
82	1	1489-0583-01	Gearbox protection			
83	1	1482-0847-01	Grease can		0.5 liter	

test