



Section: SPR 350 CARBURETTOR WALBRO WT272

Pos.	Quantity	Spare part No	Description	Kit	Notes	New
	4117					
185	1	1911-3555-01	Carburettor assy			
215	1	1911-3290-01	.Mixture screw-high			
216	1	1911-3288-01	.Mixture screw-idle			
217	1	1911-3404-01	.Spring			
218	1	1911-3405-01	.Spring			
219	1	1911-3375-01	.Inlet needle			
220	1	1911-3337-01	.Control lever			
221	1	1911-3389-01	.Throttle shaft			
223	1	1911-3410-01	.Spring			
224	1	1911-3495-01	.Screen			
225	1	1911-3291-01	.Idle speed screw			
226	1	1911-3424-01	.Cover			
227	4	1911-3285-01	.Screw			
230	1	1911-3346-01	.Fitting			
231	4	1911-3284-01	.Screw			
232	1	1911-3333-01	.Cover			
235	1	1911-3403-01	.Spring			
236	1	1911-3343-01	.Welch plug			
237	1	1911-3384-01	.Pin			
238	1	1911-3286-01	.Screw			
239	1	1911-3283-01	.Screw			
240	1	1911-3345-01	.Throttle shutter			
241	1	1911-3329-01	.Retainer			
242	1	1911-3612-01	.Diaphragm-gasket s		Inkl. 228,229,233,2	
250	1	1911-3391-01	.Plug			
251	1	1911-3332-01	.Retainer			
252	1	1911-3494-01	.Filter			
253	1	1911-3390-01	.Valve			

test