



STIGA
135E
SPARE PARTS

Section: 828, 1232 BELT TRANSMISSION

Pos.	Quantity	Spare part No	Description	Kit	Notes	New
	1817	1822				
1	1	1	1812-0207-01		Belt protection	
2	1	1	1812-0554-01		Chassie	
3A	1		1812-0428-01		Spacer	
3B		1	1812-0905-01		Engine riser	
4	3	3	9699-0026-02		Flat washer	
5	11	11	1812-0384-01		Screw	
6	11	11	1812-0385-01		Screw	
7	1	1	1812-0555-01		Plate	
8	3	3	1812-0328-01		Bushing	
9	2	2	9699-0038-02		Flat washer	
10	1	1	1812-0401-01		Pin	
11	1	1	1812-0446-01		Lever	
12	1	1	1812-0447-01		Lever	
13	9	9	9795-3631-02		Nut	
14	12	16	9683-0030-02		Lock washer	
15	1	1	9699-0028-02		Flat washer	
16	1	1	1812-0331-01		Bracket	
17	1	1	9899-3622-16		Screw	
18	4	4	9683-0035-02		Lock washer	
19	2	2	9988-3725-16		Screw	
20A	4		9987-5170-12		Screw	
20B		4	9987-5157-12		Screw	
22	1	1	1812-0427-01		Plate	
23	2	2	1812-0317-01		Spacer	
24	2	2	9987-5125-16		Screw	
25	1	1	1812-0628-01		Bolt	
26	1	1	1812-1124-01		Belt guide	
27	1	1	9988-3619-16		Screw	
28	1	1	1812-0319-01		Rod	
29	1	1	9683-0025-02		Lock washer	
30	1	1	9795-3531-02		Nut	
31	1	1	9743-3621-32		Nut	
32	1	1	1812-0321-01		Spring	
33	1	1	1812-0300-01		Bolt	
34	1	1	9699-0069-02		Flat washer	
35	1	1	1812-0421-01		Bracket	
36	2	2	1812-0322-01		Tension roller	
37	1	1	9988-3732-12		Screw	
38	1	1	9743-3721-32		Nut	
39	1	1	1812-0727-01		Spindle plate	
40	1	1	1812-0720-01		Engine pulley space	
41	1	1	1812-0333-01		Pulley	
42	1	1	1812-0334-01		Pulley	
43	1	1	1812-0283-01		Washer	
45	1	1	9987-5232-16		Bolt	
46	1	1	1812-0208-01		Tensioning arm	
47	1	1	9988-3738-12		Screw	
48	1	1	9699-0029-02		Flat washer	
49	1	1	9743-3721-32		Nut	
50	3	3	1812-1119-01		Bolt	
51	1	1	1812-9015-01		V-belt	Hjuldriivninh
52	1	1	1812-0306-01		Pulley	7"
53	1	1	1812-0307-01		Key	
54	1	1	1812-0308-01		Pulley	8.4"
55	1	1	1812-9014-01		V-belt	Snöskruv
56	1	1	1812-0424-01		Plate	
57	1	1	1812-0422-01		Bottom panel	
58	1	1	1812-0661-01		Spring	
107	4	7	9794-5131-02		Nut	
108	4	5	9743-5121-02		Nut	
109		3	9987-5125-16		Screw	
112		1	1812-1128-01		Bolt	
113	1	1	1812-0387-01		Screw	