



Section: PARK PRESIDENT 16 PARK MILLENIUM PTO-BRAKE

Pos.	Quantity		Spare part No	Description	Kit	Notes	New
	1416	1359	1360				
2	1	1	1	1134-2518-01	Console		
3	1	1	1	1134-0245-00	Shoulder screw		
4	1	1	1	9747-0831-02	Lock nut		
5	1	1	1	1134-2522-01	Plate		
6	1	1	1	1134-2520-02	Stay		
7	1	1	1	1134-2663-01	Compression spring		
8	1	1	1	1134-2529-01	Compression spring		
9	5	5	5	9699-0025-02	Washer		
10	3	3	3	9595-0110-00	Locating pin		
11	1	1	1	9595-0153-00	Locating pin		
12	1	1	1	1134-2524-01	Brake		
15	2	2	2	9959-0612-16	Screw		
16	2	2	2	9739-0631-22	Nut		
17	1	1	1	9675-0009-02	Starlock		
18	1	1	1	1134-2521-01	Shaft		
19	2	2	2	9675-0009-02	Starlock		
20	1	1	1	1134-3633-01	Spring		
21	1	1	1	1134-2519-03	Stay		
22	1	1	1	9570-0004-00	Elbow link		
23	1	1	1	9799-0631-02	Nut		

test